



Jenks Fire & Rescue

Station: **1**
Shifts Or Platoon: **A Shift**

Location: 418 W BEAVER ST Jenks OK 74037	Incident Type: 111 - Building fire
Lat/Long: N 36° 1' 13.41" W 95° 58' 25.16"	FDID: 72005 Incident #: 2018-1716 Exposure ID: 36514320 Exposure #: 0 Incident Date: 12/20/2018 Dispatch Run #: 207683
Location Type: 1 - Street address	

Report Completed by:	Ostrum , Greg	ID:	Date: 12/21/2018
Report Reviewed by:	Ostrum , Greg	ID:	Date: 12/21/2018
Report Printed by:	Ostrum, Greg	ID:	Date: 12/21/2018 Time: 15:00

Structure Type: Enclosed building	Property Use: 419 - 1 or 2 family dwelling		
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input checked="" type="checkbox"/> Cause of Ignition: Unintentional		
Aid Given or Received: None	Primary action taken: 11 - Extinguishment by fire service personnel		
Additional actions:	12 - Salvage & overhaul , 81 - Incident command		
Losses	Pre-Incident Values		
Property: \$500.00	Property: \$107,144.00	Civilian Injuries: 0	Fire Service Injuries: 0
Contents: \$0.00	Contents: \$30,000.00	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total: \$500.00	Total: \$137,144.00	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call:	4	Total # of personnel on call:	6

Narrative from dispatch:

possible electric fireits by the front doorFirst Tone Out 12202018 43758 PMNOTE BY 1144 SCHNEIDER SHANNON ON 12202018 163911MAP PAGE 19Unit 603FIRE SENIOR CAPT ON Dispatched 16400612202018 164501 Arrived Unit 601 601 FIRE CHIEFNOTE BY 1144 SCHNEIDER SHANNON ON 12202018 164421SMALL FIRE IN THE FLOORBOARDS PER 60112202018 164522 Arrived Unit T1 TRUCK 112202018 164807 Arrived Unit 603 FIRE SENIOR CAPT ON12202018 165032 Arrived Unit T2 TRUCK 2Fire Under Control At 12202018 45300 PMNOTE BY 1019 HURST JARED ON 12202018 165312FIRE KNOCKED DOWNSTILL DOING OVERHAULUser HURST JARED 12202018 171516 Cleared Unit 601 601 FIRE CHIEFUser HURST JARED 12202018 172426 Cleared Unit T2 TRUCK 2User HURST JARED 12202018 172434 Cleared Unit T1 TRUCK 1User HURST JARED 12202018 172438 Cleared Unit 603 FIRE SENIOR CAPT ON

NARRATIVE (2)

Narrative Title: n/a

Narrative Author: Owen, David

Narrative Date: 12/20/2018 18:15:13

Narrative Apparatus ID: n/a

Narrative:

Report by David Owen.

Capt. Owen arrived on scene and was requested by command to catch a hydrant. Capt. Owen pulled LDH for water supply from T-1 (1988) in a reverse lay and connected to the hydrant at Beaver and Date. Command then reported the fire under control. The supply line was not charged. Capt Owen then reported to command and assisted with overhaul as well as airing smoke out of the structure.

NARRATIVE (3)

Narrative Title: n/a

Narrative Author: Mitchell, Matthew

Narrative Date: 12/20/2018 21:15:42

Narrative Apparatus ID: n/a

Narrative:

Report written by Matthew Mitchell Driver

T1- McConnell, Todd

T2 (New T1) - Mitchell, Musselwhite

603- Owen

601- Ostrum

Dispatched to 418 W. Beaver for an electrical fire. All units responded from 121st and Vancouver where an MVC occurred that we were on scene of. New T1 responded due to Mitchells and Musselwhites gear and medical bag from R1 we're on New T1 in preparation for a road test.

601 arrived on scene to find smoke showing from under the door threshold and a very small amount of fire. T2 arrived and were instructed to bring Irons and a TIC to the door. Upon making contact with 601 Mitchell pried the door threshold, wood around the area and area between the outlet and the door frame due to the resident reporting the outlet to be hot and that he believed the fire had started in the wall. No extension found between the outlet and the location of the fire. Ostrum extinguished the fire using a very small amount of water from a crosslay from T1. From there overhaul was preformed in the threshold to find no extension. All units then cleared.

NARRATIVE (4)

Narrative Title: Cause and Determination

Narrative Author: Ostrum, Greg

Narrative Date: 12/21/2018 14:53:18

Narrative Apparatus ID: n/a

Narrative:

Dispatch information relayed to fire personnel was that we were responding to a possible electrical fire that the homeowner had tried to extinguish with a glass of water. Upon arrival 601 made contact with the homeowners and they advised that the fire appeared to have started near an outlet on the inside of the front door. The homeowner advised that they had turned off the main breaker to the home but that it had not affected the fire conditions. They also stated that they had an electrician working on that outlet the previous day and that the Christmas lights on the front porch were not operational just prior to the fire being reported.

The fire area was contained to the space between the front porch and the threshold of the front door in what appeared to be a separation between the concrete material of the porch and the wood frame of the threshold. The area was opened up by the fire attack crew using hand tools and a small amount of water was applied via 1 3/4" attack line.

During overhaul, 601 had the fire attack crews open the wall between the electrical outlet and the area of fire. The outlet was located South of the front wall approximately four feet from the front door and the area of origin. No fire conditions were found in the wall area between the outlet and fire origin.

Overhaul continued in the area of origin and material was removed until it was determined that all areas of fire spread were accounted for. During this time, no evidence of electrical wires were found in the fire area.

During the investigation, it was noted that a can of cigarette butts was located on the front porch to the South of the front door. All cigarettes in the container appeared to be fully extinguished.

Final investigation did not determine a clear cause of origin, and has been labeled "undetermined."

APPARATUS

Fire Controlled Date / Time:		12/20/2018 4:48:00 PM	
Unit	601	Unit	T1
Type:	Chief officer car	Type:	Quint
Use:	Other	Use:	Suppression
Response Mode:	()	Response Mode:	()
# of People	1	# of People	2
Alarm	12 /20/2018 16:36:19	Alarm	12 /20/2018 16:36:19
Dispatched	12 /20/2018 16:37:58	Dispatched	12 /20/2018 16:37:58
Enroute	12 /20/2018 16:38:05	Enroute	12 /20/2018 16:38:32
Arrived	12 /20/2018 16:45:01	Arrived	12 /20/2018 16:45:22
Cancelled	-- /-- /-- -- :-- :--	Cancelled	-- /-- /-- -- :-- :--
Cleared Scene	12 /20/2018 17:15:16	Cleared Scene	12 /20/2018 17:24:34
In Quarters	-- /-- /-- -- :-- :--	In Quarters	-- /-- /-- -- :-- :--
In Service	-- /-- /-- -- :-- :--	In Service	-- /-- /-- -- :-- :--
Unit	T2	Unit	603
Type:	Quint	Type:	Mobile command post
Use:	Suppression	Use:	Other
Response Mode:	()	Response Mode:	()
# of People	2	# of People	1
Alarm	12 /20/2018 16:36:19	Alarm	12 /20/2018 16:36:19
Dispatched	12 /20/2018 16:37:58	Dispatched	12 /20/2018 16:37:58
Enroute	12 /20/2018 16:38:36	Enroute	12 /20/2018 16:40:06
Arrived	12 /20/2018 16:50:32	Arrived	12 /20/2018 16:48:07
Cancelled	-- /-- /-- -- :-- :--	Cancelled	-- /-- /-- -- :-- :--
Cleared Scene	12 /20/2018 17:24:26	Cleared Scene	12 /20/2018 17:24:38
In Quarters	-- /-- /-- -- :-- :--	In Quarters	-- /-- /-- -- :-- :--
In Service	-- /-- /-- -- :-- :--	In Service	-- /-- /-- -- :-- :--
Number Of People not on apparatus: 0			

FIRE

Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Substructure area or space, crawl space	Heat Source	Undetermined
Item First Ignited	Structural member or framing	Fire Is Confined To Object Of Origin	
Type Of Material	Fiberboard, particleboard, and hardboard	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	High wind		
Human Factors Contributing	None		

STRUCTURE FIRE

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	0
Square Feet	1200	Length	
Width		Floor Of Origin	1
Fire Spread	Confined to room of origin		
Minor Damage	1	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Battery only	Detector Operation	Detector operated
Detector Effectiveness	Undetermined	Detector Failure Reason	

CUSTOM FIELDS FORM

Have you completed the narrative?	Yes
Did you page for additional staff or request standbys at the station?	Yes